Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)



## INSPECTION REPORT

Partial XXX Complete	Exploration
Inspection Date: <u>04/16/2002</u> /	Time: $2-3$ PM
	pection: 03/21/2002

Mine Name: Wildcat Loadout	County: Carbon	Permit Number: <u>C/007/033</u>					
Permittee and/or Operator's Name: Andalex Resources, Inc.							
Business Address: P.O. Box 902, Price, Uta	ah 84501						
Company Official(s): Mr. Scott Dimick, Surface Foreman							
State Official(s): Peter Hess	Federal (	Official(s): None					
Weather Conditions: Mild breezes / sunny / clear / 50 degrees Fahrenheit							
Type of Mining Activity: Underground Surface Prep Plant XXX Other							
Existing Acreage: Permitted 100 Disturb	ed 63.7 Regra	aded Seeded					
Status: Active							

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	[X]			
3.	TOPSOIL	[X]		[X]	$\Box$
4.	HYDROLOGIC BALANCE:	<del></del> -			
a.	DIVERSIONS	[X]		[X]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	$\overline{[X]}$			
d.	WATER MONITORING				
e.	EFFLUENT LIMITATIONS	[ ]	[ ]	$\Box$	. [_]
5.	EXPLOSIVES	[]	<u> </u>	[]	[]
5. ·	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[X]	[]	[]
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	[ ]	$\overline{[X]}$	[ ]
8.	NONCOAL WASTE	[X]	[ ]	$\overline{[X]}$	[]
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				<del></del>
	ENVIRONMENTAL ISSUES	[ ]	[ ]	[ ]	-[]
10.	SLIDES AND OTHER DAMAGE	[]	$\overline{[X]}$		
11.	CONTEMPORANEOUS RECLAMATION	[ ]	$\overline{[X]}$	$\overline{\Box}$	[ ]
12.	BACKFILLING AND GRADING	[ ]	$\overline{[X]}$	<u> </u>	[ ]
13.	REVEGETATION	[ ]	$\overline{[X]}$	$\overline{\Box}$	[ ]
14.	SUBSIDENCE CONTROL	[X]	1	$\overline{[X]}$	[ ]
15.	CESSATION OF OPERATIONS	. []	$\overline{[X]}$		[]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]	[ ]	[ ]	[]
b.	DRAINAGE CONTROLS	[X]	<u> </u>	<u> </u>	<u> </u>
17.	OTHER TRANSPORTATION FACILITIES	Ϊ	<u> </u>	<u> </u>	[ ]
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	<u>i i</u>	<u> </u>		[.]
19.	AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)	[ ]	ΪÌ	<u> </u>	
20.	AIR QUALITY PERMIT	<u> </u>	<u>i i</u>	<u> </u>	
21.	BONDING & INSURANCE	īi	ΓÌ	<u>[ ]</u>	[ ]

#### INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/033</u> DATE OF INSPECTION: <u>04/16/2002</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

#### 3. TOPSOIL

The permittee utilizes the area immediately west of topsoil pile "F" for storage for stoker coal. The north boundary of this coal storage area is beginning to infringe upon vegetation where the topsoil has not been removed. It was suggested to Mr. Dimick that some sort of barricade be installed at this northern boundary to prohibit equipment operators from pushing coal onto the native topsoil.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

The Carbon County area has experienced high velocity winds over the last 36-hour period. Many of the site's culverts have tumbleweed accumulations near their inlets. The permittee is working as diligently as possible to remove these, but continuing winds are making this difficult.

#### 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

All of the site's ponds were noted as dry this day. No problems were noted.

### 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

When the permittee cleans a culvert inlet or other type of diversion of sediment, the accumulation is often piled adjacent to where it was removed. This was noted at several locations. The permittee should haul the sediment cleanout material to the waste rock disposal area for final deposition.

#### 8. NONCOAL WASTE

There are several locations about the site where broken utility poles have been deposited. These should be cleaned up and removed to a permanent disposal site.

#### 14. SUBSIDENCE CONTROL

No subsidence report has been submitted for this site, as it does not engage in underground extraction activities.

Inspector's Signature: Date: April 17, 2002

Peter Hess #46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Mike Glasson, Andalex
Price Field office
O:\007033.WCL\Compliance\2002\P\_0416.doc